Peru State College Safety Committee Meeting

December 11, 2015 0900 - 1000 Campus Services Room 215

I. Call to Order by Tim Robertson, Security Supervisor

II. Roll Call

In attendance: Tim Robertson, Brent Melvin, Darrin Reeves, Laura Wittmann, Lauren Stewart, Marie Meland

Not Present: Dan Boden, Deb Morris, Hal Eltiste, Ryann Cooperbarton, Treyten Nelson

III. Old Business

- 1. AWAC and Pit Lot need more lighting
 - Darrin reported the lights on the library are fixed
 - Area is well eliminated now
- 2. Uneven bricks by Hoyt and Jindra
 - Campus Service has added to budget for next year
- 3. Old Elementary School needs signs and barricades to not enter the parking lot (erosion)
- 4. Fire Evacuation
 - How do you get a person out of a building during a fire with mobility issues
 - i. Will be adding to the emergency building plans
 - Who will help the Day Care evacuate
 - i. Will be addressed in the emergency evacuation plans for TJ Majors
 - Evacuation routes not posted in every building
 - i. Working with campus services to get building diagrams from architects
- 5. Tornado Plans
 - Where does Oak Hill and the Oak Bowl evacuate to
 - i. Suggested for Oak Bowl to Hallway of Delzell and AWAC
 - ii. Oak Hill will move to an interior room or bathroom and shelter in place
 - 1. Will post general home tornado plan in each apartment
 - Tornado Shelter locations need posted in every building
 - i. Working with campus services to get building diagrams from architects
- 6. Students need educated on importance of evacuation when fire alarms sound
 - Many students in residence halls ignore fire alarms
 - Need fire drills and training for students and staff
 - i. Will be conducting more fire drills

- ii. Will be sending information on evacuation and fire safety to RAs to address at their meetings
- 7. Dark crossing at AWAC
 - Flashing light will be installed as part of the construction plan
 - Lighting is being installed
- 8. Day Care doors need to be locked
 - Daycare installed new doorbell so doors could be locked
 - i. Doors are now locked at the Daycare

IV New Business

- 1. Sidewalks
 - Several sidewalks in need of repair
 - i. Darrin said that sidewalk repair has been discussed and is in next year's budget
- 2. Handrails at front entrance to Administration building
 - Darrin reports that campus services is looking at replacing front steps before handrails can be installed.
- 3. AWAC bridge to upper entrance is slippery and ice forms their quickly
 - Will have ice melt available and will have campus service staff place ice melt on the bridge first.
- 4. New sidewalks can't use ice melt on for one year. Need to find a product for this winter.
 - Campus Services is looking into products that can be used on the new sidewalks
 - 5. Crosswalks and pedestrian signs
 - Requesting signs on Hoyt street and 5th street marking the crosswalks
 - 6. Signs identifying buildings and parking lots
 - Requesting better identification for guest when on campus
 - i. Suggested map stands in parking lots
- V. Next Meeting January 15, 2015 at 9AM